



POLICE DEPARTMENT

NEW YORK, N.Y. 10038

**Building Maintenance Section
59-06 Laurel Hill Boulevard
Woodside, New York 11377**

June 11, 2008

Architecture & Engineering Group, P.C. AEG
11 Rice Run, East Brunswick, NJ 08816

**RE: PO79-BMABG
Fleet Services Shop #1
11 Front Street Brooklyn, NY 11201
Structural Integrity Inspection**

LETTER OF RECOMMENDATION

AEG (Architecture & Engineering Group, P.C.) was retained by New York City Police Department (NYPD) to provide Structural Integrity Inspection & Load Rating for NYPD's Service Shop #1, Vehicle Maintenance Facility at 11 Front Street, Brooklyn, NY.

AEG documented the structural components of the building because drawings were not available. They performed a thorough inspection of the structural members in the facility. Probes were taken at various locations to observe existing condition and sizes of structural members and rebar. AEG provided NYPD with an existing condition report with load rating of the existing slab. Additionally, repair procedures were included in their report for all areas requiring repairs. Also, AEG provided an engineers cost estimate to NYPD.

NYPD is satisfied with AEG's performance on the assignment. We would readily recommend AEG to another agency requiring Architectural/Engineering Services.

If you need more information, please contact me at (718) 476-8799.

Very Truly Yours,

Richard Robbins, R.A.
Chief Architect

Cc: Okey Oraedu, Project Architect